Your Logo

Service report

27/10/2026 15:10 · Karim B. · 1 photo

Customer: Résidence Les Micocouliers, bldg B
Work carried out: Re-pressurised, system bled
Follow-up:
Order expansion vessel, come back Thursday






Photo 1/1 · 27/10/2026 14:05:13 Open in Google Maps (Latitude 43.78175, Longitude 3.81342)

Comment: Pressure at 0.8 bar before the visit

Signature



Signed by Karim B. on 27/10/2026 15:09



Signed by M. Dupont on 27/10/2026 15:10